


G

WT-H

Masking Tape  
Cutout

Masking Tape  
Cutout

G



F

WT-G

9  
G

Masking Tape  
Cutout

8

7

F



G

E


F

Masking Tape  
Cutout

WT-F



Phillips screwdriver tip pont creases



E

F

D

WT-E

E

Wing Center Line

Masking Tape  
Cutout


Wing Center Line

Masking Tape  
Cutout

Cutout to allow for dihedral

D


E



C

WT-D

D



Masking Tape  
Cutout

Wing Center Line

Cutout to allow for dihedral

Masking Tape  
Cutout

Wing Center Line

C


D

B

WT-C

C

Masking Tape  
Cutout



Phillips screwdriver tip pont creases

B

C


9  
A

B


WT-B

Masking Tape  
Cutout

8



7



A

B

WT-A

A

Masking Tape  
Cutout

Masking Tape  
Cutout

A

